

2012 - Mazda6 - Transmission/ Transaxle

NO.23 TRANSAXLE OVERHEATS [AY6A-EL]

23	Transaxle overheats
DESCRIPTION	- Burnt smell emitted from transaxle. - Smoke emitted from transaxle.
POSSIBLE CAUSE	- The malfunction is restricted to the hindrance of coolant at the oil cooler. In addition, overheating of the transaxle may be caused by a malfunction of the TFT sensor. - Line pressure low - ATF level low - Incorrect accelerator opening signal - Line pressure control solenoid malfunction - Oil cooler malfunction (Foreign material mixed in with ATF) - TFT sensor malfunction - Excessive amount of ATF NOTE: - Before following the troubleshooting steps, make sure that the Automatic Transaxle On-Board Diagnostic and Automatic Transaxle Basic Inspection are conducted. (See BASIC INSPECTION [AY6A-EL].)

Diagnostic procedure

STEP	INSPECTION	ACTION
1	INSPECT TFT SENSOR AND RELATED CIRCUIT FOR MALFUNCTION Inspect the TFT sensor and related wiring harness: vibration, intermittent open/short circuit (See TRANSAXLE FLUID TEMPERATURE (TFT))	Yes Go to the next step.
		No Repair or replace part if necessary.

	SENSOR INSPECTION [AY6A-EL] .) Is it normal?		
2	INSPECT LINE PRESSURE CONTROL SOLENOID FOR MALFUNCTION - Inspect the line pressure control solenoid. (See LINE PRESSURE CONTROL SOLENOID INSPECTION [AY6A-EL] .) - Is it normal?	Yes Go to the next step.	
		No Inspect the coupler component. If normal, replace the control valve body. (See CONTROL VALVE BODY REMOVAL/ INSTALLATION [AY6A-EL] .)	
3	VERIFY IF MALFUNCTION CAUSE IS OIL COOLER PIPE OR TRANSAXLE - Inspect for bending, damage, corrosion or kinks of the oil cooler pipes. - Are oil cooler pipes normal?	Yes Replace the transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [AY6A-EL] .)	
		No Replace any malfunctioning parts.	
4	- Verify test results. - If normal, return to the diagnostic index to service any additional symptoms. - If malfunction remains, inspect the related Service Bulletins and/or On-line Repair Information and perform repair or diagnosis. - If the vehicle is repaired, troubleshooting completed. - If the vehicle is not repaired or additional diagnostic information is not available, replace the TCM.		

2012 - Mazda6 - Transmission/ Transaxle

NO.23 TRANSAXLE OVERHEATS [AY6A-EL]

23	Transaxle overheats
DESCRIPTION	- Burnt smell emitted from transaxle. - Smoke emitted from transaxle.
POSSIBLE CAUSE	- The malfunction is restricted to the hindrance of coolant at the oil cooler. In addition, overheating of the transaxle may be caused by a malfunction of the TFT sensor. - Line pressure low - ATF level low - Incorrect accelerator opening signal - Line pressure control solenoid malfunction - Oil cooler malfunction (Foreign material mixed in with ATF) - TFT sensor malfunction - Excessive amount of ATF NOTE: - Before following the troubleshooting steps, make sure that the Automatic Transaxle On-Board Diagnostic and Automatic Transaxle Basic Inspection are conducted. (See BASIC INSPECTION [AY6A-EL].)

Diagnostic procedure

STEP	INSPECTION	ACTION
1	INSPECT TFT SENSOR AND RELATED CIRCUIT FOR MALFUNCTION Inspect the TFT sensor and related wiring harness: vibration, intermittent open/short circuit (See TRANSAXLE FLUID TEMPERATURE (TFT))	Yes Go to the next step. No Repair or replace part if necessary.

	SENSOR INSPECTION [AY6A-EL] .) Is it normal?		
2	INSPECT LINE PRESSURE CONTROL SOLENOID FOR MALFUNCTION - Inspect the line pressure control solenoid. (See LINE PRESSURE CONTROL SOLENOID INSPECTION [AY6A-EL] .) - Is it normal?	Yes Go to the next step.	
		No Inspect the coupler component. If normal, replace the control valve body. (See CONTROL VALVE BODY REMOVAL/ INSTALLATION [AY6A-EL] .)	
3	VERIFY IF MALFUNCTION CAUSE IS OIL COOLER PIPE OR TRANSAXLE - Inspect for bending, damage, corrosion or kinks of the oil cooler pipes. - Are oil cooler pipes normal?	Yes Replace the transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [AY6A-EL] .)	
		No Replace any malfunctioning parts.	
4	- Verify test results. - If normal, return to the diagnostic index to service any additional symptoms. - If malfunction remains, inspect the related Service Bulletins and/or On-line Repair Information and perform repair or diagnosis. - If the vehicle is repaired, troubleshooting completed. - If the vehicle is not repaired or additional diagnostic information is not available, replace the TCM.		