

[< Previous](#) [Next >](#)

2012 - Mazda6 - Transmission/ Transaxle

NO.19 EXCESSIVE SHIFT SHOCK ON TORQUE CONVERTER CLUTCH (TCC) [FS5A-EL]

19	Excessive shift shock on torque converter clutch (TCC)
DESCRIPTION	• Strong shock is felt when the TCC is engaged.
POSSIBLE CAUSE	• The troubleshooting flow is the same as No.16 "Judder upon torque converter clutch (TCC) operation".

[< Previous](#) [Next >](#)

[Back to Top](#)

© 2012 Mazda North American Operations, U.S.A.

[< Previous](#) [Next >](#)

2012 - Mazda6 - Transmission/ Transaxle

NO.19 EXCESSIVE SHIFT SHOCK ON TORQUE CONVERTER CLUTCH (TCC) [FS5A-EL]

19	Excessive shift shock on torque converter clutch (TCC)
DESCRIPTION	• Strong shock is felt when the TCC is engaged.
POSSIBLE CAUSE	• The troubleshooting flow is the same as No.16 "Judder upon torque converter clutch (TCC) operation".

[< Previous](#) [Next >](#)

[Back to Top](#)

© 2012 Mazda North American Operations, U.S.A.