

2012 - Mazda6 - Restraints

DTC B1193:00

System Malfunction Location

- SAS control module operation (deployment)

Detection Condition

- The SAS control module has enabled the air bag module or pre-tensioner seat belt to operate (deploy)

Possible Causes

- SAS control module operate (deploy) enable memory has exceeded upper limit
- SAS control module malfunction

Diagnostic Procedure

Inspection
Replace the SAS control module. (See SAS CONTROL MODULE REMOVAL/ INSTALLATION .)

2012 - Mazda6 - Restraints

DTC B1193:00

System Malfunction Location

- SAS control module operation (deployment)

Detection Condition

- The SAS control module has enabled the air bag module or pre-tensioner seat belt to operate (deploy)

Possible Causes

- SAS control module operate (deploy) enable memory has exceeded upper limit
- SAS control module malfunction

Diagnostic Procedure

Inspection
Replace the SAS control module. (See SAS CONTROL MODULE REMOVAL/ INSTALLATION.)