

2012 - Mazda6 - Body and Accessories

No.7 PASSENGER'S DOOR GLASS OPERATES ACCIDENTALLY [POWER WINDOW SYSTEM (EXTERIOR OPEN FUNCTION)]

7	Passenger's door glass operates accidentally
POSSIBLE CAUSE	• Power window subswitch (passenger's) malfunction

Diagnostic procedure

ACTION
Inspect the power window subswitch of the passenger's door glass and repair or replace (See POWER WINDOW SUBSWITCH INSPECTION .)

2012 - Mazda6 - Body and Accessories

No.7 PASSENGER'S DOOR GLASS OPERATES ACCIDENTALLY [POWER WINDOW SYSTEM (EXTERIOR OPEN FUNCTION)]

7	Passenger's door glass operates accidentally
POSSIBLE CAUSE	• Power window subswitch (passenger's) malfunction

Diagnostic procedure

ACTION
Inspect the power window subswitch of the passenger's door glass and repair or replace (See POWER WINDOW SUBSWITCH INSPECTION .)