


2012 - Mazda6 - Body and Accessories

VANITY MIRROR ILLUMINATION INSPECTION

- 1. Remove the sunvisor. (See [SUNVISOR REMOVAL/ INSTALLATION.](#))
- 2. Verify that the continuity between the vanity mirror illumination terminals is as indicated in the table.



- If not as indicated in the table, inspect the bulb. If there is no malfunction, replace the sunvisor.

: Bulb

Vanity mirror cover condition	Terminal	
	A	B
OPEN		
CLOSED		