


2012 - Mazda6 - HVAC

FRONT BLOWER MOTOR INSPECTION [FULL-AUTO AIR CONDITIONER]

1. Connect battery positive voltage to blower motor terminal A, connect terminal B to ground, and then verify its operation.




- If there is any malfunction, replace the blower motor.

2012 - Mazda6 - HVAC

FRONT BLOWER MOTOR INSPECTION [FULL-AUTO AIR CONDITIONER]

1. Connect battery positive voltage to blower motor terminal A, connect terminal B to ground, and then verify its operation.



- If there is any malfunction, replace the blower motor.