

2012 - Mazda6 - Body and Accessories

DTC U3000:41 [INSTRUMENT CLUSTER]

DESCRIPTION	Instrument cluster internal malfunction
DETECTION CONDITION	Malfunction in internal circuit detected
POSSIBLE CAUSE	Instrument cluster internal malfunction

Diagnostic Procedure

Step	Inspection	Action
1	PERFORM DTC INSPECTION - Clear the DTC from the instrument cluster memory using the M-MDS. (See CLEARING DTC [INSTRUMENT CLUSTER].) - Perform the instrument cluster DTC inspection using the M-MDS. (See DTC INSPECTION [INSTRUMENT CLUSTER].) - Is the same DTC present?	Yes Replace the instrument cluster, then go to the next step. (See INSTRUMENT CLUSTER REMOVAL/ INSTALLATION .)
		No Go to the next step.
2	VERIFY THAT NO OTHER DTCs ARE RECORDED Are any DTCs present?	Yes Go to the applicable DTC inspection. (See DTC TABLE [INSTRUMENT CLUSTER] .)
		No DTC troubleshooting completed.

2012 - Mazda6 - Body and Accessories

DTC U3000:41 [INSTRUMENT CLUSTER]

DESCRIPTION	Instrument cluster internal malfunction
DETECTION CONDITION	Malfunction in internal circuit detected
POSSIBLE CAUSE	Instrument cluster internal malfunction

Diagnostic Procedure

Step	Inspection	Action
1	PERFORM DTC INSPECTION - Clear the DTC from the instrument cluster memory using the M-MDS. (See CLEARING DTC [INSTRUMENT CLUSTER].) - Perform the instrument cluster DTC inspection using the M-MDS. (See DTC INSPECTION [INSTRUMENT CLUSTER].) - Is the same DTC present?	Yes Replace the instrument cluster, then go to the next step. (See INSTRUMENT CLUSTER REMOVAL/ INSTALLATION .)
		No Go to the next step.
2	VERIFY THAT NO OTHER DTCs ARE RECORDED Are any DTCs present?	Yes Go to the applicable DTC inspection. (See DTC TABLE [INSTRUMENT CLUSTER] .)
		No DTC troubleshooting completed.