


2012 - Mazda6 - Body and Accessories

STEERING ANGLE SENSOR INSPECTION

- 1. Remove the column cover. (See [COLUMN COVER REMOVAL/ INSTALLATION](#).)
- 2. Turn the steering wheel to the right and left, and verify that the voltage and pulses at the terminals are as shown in the figure.
 - If not as specified, replace the combination switch.



2012 - Mazda6 - Body and Accessories

STEERING ANGLE SENSOR INSPECTION

- 1. Remove the column cover. (See [COLUMN COVER REMOVAL/ INSTALLATION](#).)
- 2. Turn the steering wheel to the right and left, and verify that the voltage and pulses at the terminals are as shown in the figure.
 - If not as specified, replace the combination switch.

