

2012 - Mazda6 - Engine

DTC P0610:00 [MZR 2.5]

DTC P0610:00	PCM vehicle configuration error
DETECTION CONDITION	- PCM data configuration error. Diagnostic support note - This is a continuous monitor (CCM). - The MIL illuminates if the PCM detects the above malfunction condition in the first drive cycle. - FREEZE FRAME DATA (Mode 2)/Snapshot data is available. - The DTC is stored in PCM memory.
POSSIBLE CAUSE	- Configuration procedure has not been completed - PCM malfunction

Diagnostic procedure

STEP	INSPECTION	ACTION
1	VERIFY FREEZE FRAME DATA (MODE 2)/ SNAPSHOT DATA HAS BEEN RECORDED	Yes Go to the next step.
	Has the FREEZE FRAME DATA (Mode 2)/snapshot data been recorded?	No Record the FREEZE FRAME DATA (Mode 2)/snapshot data on the repair order, then go to the next step.
2	VERIFY RELATED REPAIR INFORMATION AVAILABILITY	Yes Perform repair or diagnosis according to the available repair information.
	- Verify related Service Bulletins and/or on-line repair information availability. - Is any related repair information available?	No Go to the next step.
3	PERFORM PCM CONFIGURATION Perform the PCM	Yes Perform the PCM configuration again, then go to the next step.

	configuration. (See PCM CONFIGURATION [MZR 2.5].) • Clear the DTC from the PCM memory using the M-MDS. (See AFTER REPAIR PROCEDURE [MZR 2.5].) • Retrieve the DTC using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [MZR 2.5].) • Is the same DTC present?		(See PCM CONFIGURATION [MZR 2.5].)
		No	Go to Step 5.
4	VERIFY DTC TROUBLESHOOTING COMPLETED • Clear the DTC from the PCM memory using the M-MDS. (See AFTER REPAIR PROCEDURE [MZR 2.5].) • Perform the KOEO or KOER self test. (See KOEO/ KOER SELF TEST [MZR 2.5].) • Is the same DTC present?	Yes	Replace the PCM, then go to the next step. (See PCM REMOVAL/ INSTALLATION [MZR 2.5].)
		No	Go to the next step.
5	VERIFY AFTER REPAIR PROCEDURE • Perform the "AFTER REPAIR PROCEDURE". (See AFTER REPAIR PROCEDURE [MZR 2.5].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [MZR 2.5].)
		No	DTC troubleshooting completed.

2012 - Mazda6 - Engine

DTC P0610:00 [MZR 2.5]

DTC P0610:00	PCM vehicle configuration error
DETECTION CONDITION	- PCM data configuration error. Diagnostic support note - This is a continuous monitor (CCM). - The MIL illuminates if the PCM detects the above malfunction condition in the first drive cycle. - FREEZE FRAME DATA (Mode 2)/Snapshot data is available. - The DTC is stored in PCM memory.
POSSIBLE CAUSE	- Configuration procedure has not been completed - PCM malfunction

Diagnostic procedure

STEP	INSPECTION	ACTION
1	VERIFY FREEZE FRAME DATA (MODE 2)/ SNAPSHOT DATA HAS BEEN RECORDED	Yes Go to the next step.
	Has the FREEZE FRAME DATA (Mode 2)/snapshot data been recorded?	No Record the FREEZE FRAME DATA (Mode 2)/snapshot data on the repair order, then go to the next step.
2	VERIFY RELATED REPAIR INFORMATION AVAILABILITY	Yes Perform repair or diagnosis according to the available repair information.
	- Verify related Service Bulletins and/or on-line repair information availability. - Is any related repair information available?	No Go to the next step.
3	PERFORM PCM CONFIGURATION Perform the PCM	Yes Perform the PCM configuration again, then go to the next step.

	configuration. (See PCM CONFIGURATION [MZR 2.5].) • Clear the DTC from the PCM memory using the M-MDS. (See AFTER REPAIR PROCEDURE [MZR 2.5].) • Retrieve the DTC using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [MZR 2.5].) • Is the same DTC present?		(See PCM CONFIGURATION [MZR 2.5].)
		No	Go to Step 5.
4	VERIFY DTC TROUBLESHOOTING COMPLETED • Clear the DTC from the PCM memory using the M-MDS. (See AFTER REPAIR PROCEDURE [MZR 2.5].) • Perform the KOEO or KOER self test. (See KOEO/ KOER SELF TEST [MZR 2.5].) • Is the same DTC present?	Yes	Replace the PCM, then go to the next step. (See PCM REMOVAL/ INSTALLATION [MZR 2.5].)
		No	Go to the next step.
5	VERIFY AFTER REPAIR PROCEDURE • Perform the "AFTER REPAIR PROCEDURE". (See AFTER REPAIR PROCEDURE [MZR 2.5].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [MZR 2.5].)
		No	DTC troubleshooting completed.