

2012 - Mazda6 - Body and Accessories

DTC: 26:Er86, DEVICE CORD 26/ ERROR CORD 86 [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)]

DESCRIPTION	Bluetooth unit internal malfunction
DETECTION CONDITION	Bluetooth unit detects the internal malfunction.
POSSIBLE CAUSE	Bluetooth unit malfunction

Diagnostic Procedure

Step	Inspection	Action
1	CONFIRM Bluetooth UNIT DTC - Clear the DTC from the Bluetooth unit memory. (See CLEARING DTC [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)] .) - Perform the Bluetooth unit DTC inspection. (See DTC INSPECTION [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)] .) - Is the same DTC present?	Yes Replace the Bluetooth unit, then go to the next step. (See Bluetooth UNIT REMOVAL/ INSTALLATION .)
		No Go to the next step.
2	VERIFY THAT NO OTHER DTCs ARE RECORDED Are any DTCs present?	Yes Go to the applicable DTC inspection. (See DTC TABLE [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)] .)
		No DTC troubleshooting completed.

2012 - Mazda6 - Body and Accessories

DTC: 26:Er86, DEVICE CORD 26/ ERROR CORD 86 [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)]

DESCRIPTION	Bluetooth unit internal malfunction
DETECTION CONDITION	Bluetooth unit detects the internal malfunction.
POSSIBLE CAUSE	Bluetooth unit malfunction

Diagnostic Procedure

Step	Inspection	Action
1	CONFIRM Bluetooth UNIT DTC - Clear the DTC from the Bluetooth unit memory. (See CLEARING DTC [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)] .) - Perform the Bluetooth unit DTC inspection. (See DTC INSPECTION [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)] .) - Is the same DTC present?	Yes Replace the Bluetooth unit, then go to the next step. (See Bluetooth UNIT REMOVAL/ INSTALLATION .)
		No Go to the next step.
2	VERIFY THAT NO OTHER DTCs ARE RECORDED Are any DTCs present?	Yes Go to the applicable DTC inspection. (See DTC TABLE [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)] .)
		No DTC troubleshooting completed.

